

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

2/27/05
RECEIVED
FEB 02 2005
DIV. OF OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/2004 To (mo./yr.) 12/2004
2. DOGM File Number (Mine No): 5230060
3. Mine Name: Mile high #1
4. Mineral(s) Mined (or permitted to mine): Topaz, Pseudobrookite
5. Type of mine: ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
____ 1/4, ____ 1/4, SW 1/4, Section 15, Township 12S, Range 11W
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
7. Name of Operator or Company: William Chirnside
8. Permanent Street Address: 2157 S Cole Ct
City, State, Zip: Lakewood, CO 80228-4610
Phone: (303) 989-8748 Fax: _____
9. Company Representative (or designated operator):
Name: _____
Title: _____
Business Address: _____
City, State, Zip: _____
Phone: _____ Fax: _____
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? 3 flats of Mineral specimens

TWSPCT

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

1 yd³ of rock from the bottom of the west face of the pit in the solid rock knob to the south of the reclaimed original discovery cut.

5. How much **additional acreage** was disturbed during the past year? 0

6. How much acreage was **reclaimed** during the past year? 10 yd²

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Revegetation of the discovery cut is proceeding

8. What is the **total** disturbed acreage of entire project at years end? < 0.02

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

continuing as in past years with hand tools and methods. The "Pink Pit" in the south end of the claim is being filled.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): William Chirside

Title of Operator: claimant/operator

Signature of Operator: William Chirside

Date: January 29, 2005